



Funded by ETDD Brownfields Program Assessment Grant


East Tennessee Development District PO Box 249 216 Corporate Place Alcoa, TN 37717





Prepared by S&ME, Inc. 6515 Nightingale Lane Knoxville, TN 37909



















| Site | 1029 S Main |
|-----------------------------------|--|
| Street | 1029 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | NELSON RONALD MICHAEL NELSON |
| Parcel ID | 018E B 015.00 |
| Owner Street | PO BOX 1215 |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map | Figure 4 |
| Figure | · |
| Acreage | 0.48 |
| Description | Property lies at the intersection between S. Main Street and Old Lake City Highway. Southern building is two attached structures of concrete block construction, brick siding on the front façade and metal roof. Northern building is a former commercial garage. Railroad is to the west and a former gas station property is to the east. |
| Square Footage | Two Buildings; 2220 SF and 1980 SF |
| Year Constructed | Two Buildings; 1949 and 1961 |
| Regulatory Status of the Site | No regulatory records found. |
| Adjoining/Adjacent Properties | CSX Railway borders to the west. Adjacent property S of site is a former drycleaner. Across Hwy 25W (S Main St.) to the SW of site is a former bus depot with a petroleum UST/LUST status as 1a Completed Tank Closure. |
| Aerial Photographs | 1940-1952 – Site appears vacant/undeveloped. 1952-1956 – Single building on site, unknown use. 1976-2016 – Two buildings on site, appears to be in use through 2012 with part of property being used for cars/equipment parking and storage. |
| City Directories | 1992-1995 – Address not listed. 2000-2010 – The Engine Room. 2014-2017 – Address not listed |
| Sanborn Maps | Unmapped Property |
| Current Zoning | M-1 (Industrial District) |
| Current Site Use | Vacant |
| Former Use | Unknown |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues/Challenges | Evidence of former auto repair on subject property and potential for residual petroleum contamination. Potential for vapor intrusion issues. Potential for lead based paint and asbestos hazards due to age of buildings. |
| Phase I ESA Fee | 4000 |
| Phase II ESA Fee | \$12,000 - \$22,000 |
| ACM/LBP Survey | \$3,000 - \$6,000 |



| Street 908 S. MAIN STREET City, State, Zip Rocky Top, TN, 37769 County Anderson Owner DUNN DOROTHY Parcel ID 018E F 007.00 Owner Street PO BOX 1096 Area of Interest & Associated Map Figure 3 Acreage 7199 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street, Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning Carlot State Use Vacant Current Ste Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B No mapped wetlands on the site. Water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. | | |
|--|-----------------------------------|--|
| County Anderson Owner DUNN DOROTHY Parcel ID 018E F007.00 Owner Street PO BOX 1096 Owner City, State, Zip ROCKY TOP, TN 37769 Owner City, State, Zip ROCKY TOP, TN 37769 Figure 3 Figure 3 Figure 3 Figure 3 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage PY ABOS Square Footage None identified of environmental concern. Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 - Site appears svacant, however concrete pad/parking area visible. 1982-2016 - Building visible on site, business function. No major changes to present. City Directories 1992 - Henderson Upholstery, The Unique Bourlique 1995 - Bobby Henderson Upholstery 2000 - Smokers Tobacco Outlet II. 2010-2017 - Address not listed Sanborn Maps 1940 - No building Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood No mapped wetlands on the site. Water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against buildings. Phase I ESA Fee | Site | 908 S Main |
| Anderson DUNN DOROTHY | Street | 908 S. MAIN STREET |
| Owner Street DI O ORD 198 F 007.00 Owner City, State, Zip ROCKY TOP, TN 37769 Area of Interest & Associated Map Figure 3 Figure BOSCription Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street, Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – No building Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available Water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting varies in mediately against buildings foundations. Potential for lead based paint and asbestos hazards due to age of buildings. | City, State, Zip | Rocky Top, TN, 37769 |
| Parcel ID Owner Street PO BOX 1096 Owner City, State, Zip ROCKY TOP, TN 37769 Figure 3 Figure 3 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – 1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase I ESA Fee | County | Anderson |
| Owner Street Owner City, State, Zip Area of Interest & Associated Map Figure Acreage Figure Acreage Osciption Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street, Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Pyear Constructed Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 \$12,000 – \$22,000 | Owner | DUNN DOROTHY |
| Acreage 0,31 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. ERMA/Flood Zone B National Wetland Inventory Maps Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase I ESA Fee \$4,000 | Parcel ID | 018E F 007.00 |
| Figure Acreage 0.31 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 – No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$4,000 | Owner Street | PO BOX 1096 |
| Figure Acreage 0.31 Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase I ESA Fee \$12,000 - \$22,000 | Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Acreage Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 – Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning Current Zoning Current Site Use Vacious including general store, storage, Ambulance operations. FEMA/Flood Vacant Former Use No mapped wetlands on the site. Utilities Available Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee Phase I ESA Fee \$4,000 | Area of Interest & Associated Map | Figure 2 |
| Property lies directly off S. Main Street, across from the parking lot fronting S. Main Street. Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase I ESA Fee \$12,000 - \$22,000 | Figure | Figure 5 |
| Concrete block construction, brick façade. Several connected buildings and outbuildings on site. Creek runs along backside of building posing risk of erosion. Square Footage 4806 Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 — Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning Corrent Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase I ESA Fee \$12,000 - \$22,000 | Acreage | 0.31 |
| Year Constructed 1947 Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Environmental Issues/Challenges Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Description | Concrete block construction, brick façade. Several connected buildings and outbuildings |
| Regulatory Status of the Site No regulatory records found Adjoining/Adjacent Properties None identified of environmental concern. Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 Building visible on site, business function. No major changes to present. City Directories 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Square Footage | 4806 |
| Adjoining/Adjacent Properties None identified of environmental concern. 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 | Year Constructed | 1947 |
| Aerial Photographs 1940-1976 – Site appears vacant, however concrete pad/parking area visible. 1982-2016 - Building visible on site, business function. No major changes to present. 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Regulatory Status of the Site | No regulatory records found |
| Aerial Photographs — Building visible on site, business function. No major changes to present. 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed Sanborn Maps 1940 - No building Current Zoning C-2 (Tourist Commercial District) Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Adjoining/Adjacent Properties | None identified of environmental concern. |
| Sanborn Maps 1940 - No building | Aerial Photographs | |
| Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available Environmental Issues/Challenges Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | City Directories | |
| Current Site Use Vacant Former Use Various including general store, storage, Ambulance operations. FEMA/Flood Zone B National Wetland Inventory Maps No mapped wetlands on the site. Utilities Available water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Sanborn Maps | 1940 - No building |
| Various including general store, storage, Ambulance operations. Zone B | Current Zoning | C-2 (Tourist Commercial District) |
| FEMA/FloodZone BNational Wetland Inventory MapsNo mapped wetlands on the site.Utilities Availablewater, sewer, electric, gasEnvironmental Issues/ChallengesAbove-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings.Phase I ESA Fee\$4,000Phase II ESA Fee\$12,000 - \$22,000 | Current Site Use | Vacant |
| National Wetland Inventory Maps Water, sewer, electric, gas Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Former Use | Various including general store, storage, Ambulance operations. |
| Utilities Availablewater, sewer, electric, gasEnvironmental Issues/ChallengesAbove-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings.Phase I ESA Fee\$4,000Phase II ESA Fee\$12,000 - \$22,000 | FEMA/Flood | Zone B |
| Above-ground tank on site in need of further investigation. Potential for residual petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase II ESA Fee \$4,000 \$12,000 - \$22,000 | National Wetland Inventory Maps | No mapped wetlands on the site. |
| petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. Potential for lead based paint and asbestos hazards due to age of buildings. Phase I ESA Fee \$4,000 Phase II ESA Fee \$12,000 - \$22,000 | Utilities Available | water, sewer, electric, gas |
| Phase II ESA Fee \$12,000 - \$22,000 | Environmental Issues/Challenges | petroleum contamination. Unnamed tributary to Coal Creek along NE border of property causing bank erosion and undercutting visible immediately against building foundations. |
| | Phase I ESA Fee | \$4,000 |
| ACM/LBP Survey \$3,000 - \$6,000 | Phase II ESA Fee | \$12,000 - \$22,000 |
| | ACM/LBP Survey | \$3,000 - \$6,000 |



| Site | 701 S Main |
|-----------------------------------|---|
| Street | 701 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | NELSON BARRY N |
| Parcel ID | 018E B 007.00 |
| Owner Street | 351 OLD LAKE CITY HWY |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map | F: 2 |
| Figure | Figure 3 |
| Acreage | 0.15 |
| Description | Property lies at the intersection between S. Main Street and E. 6th Street. Small block |
| Description | building with plyboard visible at top third. Grass lot. |
| Square Footage | 1800 |
| Year Constructed | Unknown |
| Regulatory Status of the Site | No regulatory records found |
| | Property immediately adjacent to the South, currently a grocery store, was a historic gas |
| Adjoining/Adjacent Properties | station and is listed under the Historic Auto, UST/LUST databases. Four USTs of varying |
| , , , , | capacities are listed as "Permanently Out of Use". |
| | 1940 – Low resolution aerial photos in downtown area, no discernable details. 1956- |
| Aerial Photographs | 1993 – Small building on site. Possible shed/temporary structure, unknown use. 1997 - |
| | 2016 – Larger development and structure on site, evidence of commercial uses. |
| | 1992 – Address not listed 1995 – Convenient Food Mart 2000 – Dairy Mart 2010-2017 – |
| City Directories | Address not listed |
| Sanborn Maps | 1940 - Private Dwelling |
| Current Zoning | C-2 (Tourist Commercial District) |
| Current Site Use | Vacant |
| Former Use | Unknown |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| | Possible residual netroloum contamination related to former LICTs an adiability answer. |
| Environmental Issues/Challenges | Possible residual petroleum contamination related to former USTs on adjoining property. Potential for lead based paint and asbestos hazards due to age of buildings. |
| | rotential for lead based paint and aspestos nazards due to age of buildings. |
| Phase I ESA Fee | \$4,000 |
| | |
| Phase II ESA Fee | \$10,000 - \$18,000 |



| Site | 522 S Main |
|---|---|
| Street | 522 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | NELSON DONALD GLENN |
| Parcel ID | 018E C 024.00 |
| Owner Street | 114 SAVANNAH LN |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map Figure | Figure 3 |
| Acreage | 0.07 |
| Description | Property lies at the intersection between S. Main Street and 5th Street. Multi-use building (historically, and possibly current). Brick building (block?). |
| Square Footage | 2154 |
| Year Constructed | 1924 |
| Regulatory Status of the Site | No regulatory records found |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1940 – Low resolution aerial photos in downtown area, no discernable details. 1993 – Developed site, however low resolution aerial photos in downtown area 2016 – Site developed, appears to have varied commercial uses. |
| City Directories | 1992-2014 – Lake City TV Sales & Service 2017 – Address not listed |
| Sanborn Maps | 1940 - Store, with Private Dwelling adjacent/attached |
| Current Zoning | C-4 (Central Downtown Business District) |
| Current Site Use | Unknown, believed to be vacant. |
| Former Use | Unknown |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues/Challenges | Potential for lead based paint and asbestos hazards due to age of buildings. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$10,000 - \$18,000 |
| ACM/LBP Survey | \$3,000 - \$6,000 |



| Site | Coin Laundry |
|---|---|
| Street | 320 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | BAILEY ROCKY L |
| Parcel ID | 018D E 017.00 |
| Owner Street | 3484 BRICEVILLE HWY |
| Owner City, State, Zip | BRICEVILLE, TN 37710 |
| Area of Interest & Associated Map Figure | Figure 2 |
| Acreage | 0.15 |
| Description | Property lies directly off S. Main Street. Long, narrow property with block construction and brick façade. Metal roof with sheet metal siding along back and sides of building. Parking lot associated with lot behind building. |
| Square Footage | 8910 **part of original structure possibly demolished. |
| Year Constructed | 1925 |
| Regulatory Status of the Site | No regulatory records found |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1940-1976 – Low resolution aerial photos in downtown area, no discernable details. 1982-2016 – Downtown district well developed. All building within the area of interest constructed and operational. |
| City Directories | 1992 – Henderson Upholstery, The Unique Boutique 1995 – Bobby Henderson Upholstery 2000 – Smokers Tobacco Outlet II. 2010-2017 – Address not listed |
| Sanborn Maps | 1940 - Restaurant and attached dwelling located on site. |
| Current Zoning | C-4 (Central Downtown Business District) |
| Current Site Use | Vacant |
| Former Use | Laundromat |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| | |
| Environmental Issues/Challenges | Possible residual petroleum contamination related to former USTs on adjoining property. Potential for lead based paint and asbestos hazards due to age of buildings. |
| Environmental Issues/Challenges Phase I ESA Fee | Potential for lead based paint and asbestos hazards due to age of buildings. \$4,000 |
| | Potential for lead based paint and asbestos hazards due to age of buildings. |



| Site | 317 S Main |
|--|--|
| Street | 317 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | COOPER MARC ETUX C/O NOLA I COOPER |
| Parcel ID | 018D D 013.00 |
| Owner Street | 317 MAIN STREET |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map | Figure 2 |
| Figure | rigule 2 |
| Acreage | 0.15 |
| | Property lies directly off S. Main Street. Block construction with brick façade. Building |
| Description | attached to adjacent on either side. Possible residential use near. No parking lot |
| | associated directly with building. |
| Square Footage | 4675 |
| Year Constructed | 1940 |
| Regulatory Status of the Site | No regulatory records found |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| | 1940-1976 – Low resolution aerial photos in downtown area, no discernable details. |
| Aerial Photographs | 1982-2016 – Downtown district well developed. All building within the area of interest |
| | constructed and operational. |
| | constructed and operational. |
| City Directories | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed |
| City Directories Sanborn Maps | |
| - | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed |
| Sanborn Maps | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. |
| Sanborn Maps Current Zoning | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) |
| Sanborn Maps Current Zoning Current Site Use | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. |
| Sanborn Maps Current Zoning Current Site Use Former Use | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. Hotel |
| Sanborn Maps Current Zoning Current Site Use Former Use FEMA/Flood | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. Hotel Zone B |
| Sanborn Maps Current Zoning Current Site Use Former Use FEMA/Flood National Wetland Inventory Maps | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. Hotel Zone B No mapped wetlands on the site. |
| Sanborn Maps Current Zoning Current Site Use Former Use FEMA/Flood National Wetland Inventory Maps Utilities Available | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. Hotel Zone B No mapped wetlands on the site. water, sewer, electric, gas |
| Sanborn Maps Current Zoning Current Site Use Former Use FEMA/Flood National Wetland Inventory Maps Utilities Available Environmental Issues/Challenges | 1992-1995 – Chapman's Custom Cabinets 2000-2017 – Address not listed 1940 - Building not shown. Lot vacant between store fronts, hotel, car garages. C-4 (Central Downtown Business District) Believed Vacant. Possible residential use on 2nd floor. Hotel Zone B No mapped wetlands on the site. water, sewer, electric, gas Potential for lead based paint and asbestos hazards due to age of buildings. |



| Site | 310 S Main |
|---|---|
| | 5 IU 5 IVIAIII |
| Street | 310 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | HORTON MISTY AND TONY LINDSAY |
| Parcel ID | 018D E 019.00 |
| Owner Street | PO BOX 546 |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map Figure | Figure 2 |
| Acreage | 0.47 |
| Description | Property lies directly off S. Main Street. Two buildings structurally connected with block construction and brick façade. Parking lot attached to property. |
| Square Footage | 9470 |
| Year Constructed | 1933 |
| Regulatory Status of the Site | No regulatory records found |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1940-1976 – Low resolution aerial photos in downtown area, no discernable details. 1982-2016 – Downtown district well developed. All building within the area of interest constructed and operational. |
| City Directories | 1992 – Address not listed 1995-2014 – Ford Furniture Co., Lindsay's Furniture & Appliances 2017 – Address not listed |
| Sanborn Maps | 1940 - Single store on site, consisting of roughly half of current structures on site. |
| Current Zoning | C-4 (Central Downtown Business District) |
| Current Site Use | Vacant |
| Former Use | Furniture, Carpet and Appliance |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues/Challenges | Potential for lead based paint and asbestos hazards due to age of buildings. |
| Phase I ESA Fee | \$4,000 |
| i ilase i LSA i ee | |
| Phase II ESA Fee | \$5,000 - \$10,000 |



| Site | MARTIN FUNERAL HOME |
|-----------------------------------|--|
| Street | 225 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | WILSON VIRGIL E AND WIFE BARBARA |
| Parcel ID | 018D D 007.00 |
| Owner Street | 1816 ALABAMA STREET |
| Owner City, State, Zip | SEYMOUR, TN 37865 |
| Area of Interest & Associated Map | Figure 2 |
| Figure | Figure 2 |
| Acreage | 0.61 |
| Description | Property lies at the intersection between S. Main Street and W. 2nd Street. Large structure with large parking lot. Multiple phases of construction visible in the building. Former residential and commercial uses at varying points in the history. |
| Square Footage | 6866 |
| Year Constructed | 1920 |
| Regulatory Status of the Site | Former funeral home site, listed with a historic gasoline UST of unknown capacity; regulatory status listed as permanently out of use. |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1940-1976 – Low resolution aerial photos in downtown area, no discernable details. 1982- 2016 – Downtown district well developed. All building within the area of interest constructed and operational. |
| City Directories | 1992 – Martin Funeral Home 1995-2000 – Address not listed 2005 – The Tool Shack, Raymond R. Jobe 2010 – The Tool Shack 2014-2017 – Address not listed |
| Sanborn Maps | 1940 - Funeral Home in operation, Undertaker services toward Main St. with private residence attached. Adjacent structure labeled as 'filling station' and shown with concrete floor. Possible location for 'Permanently Out of Use' UST |
| Current Zoning | C-4 (Central Downtown Business District) |
| Current Site Use | Vacant |
| Former Use | Funeral Home; burial/cremation services |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues/Challenges | Residual contamination related to former embalming/cremation activities on the site. Evidence of a fire within the building raises concern for integrity of the structure. Potential for lead based paint and asbestos hazards due to age of buildings. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$8,000 - \$15,000 |
| ACM/LBP Survey | \$6,000 - \$8,000 |





| CONTROL OF THE CONTRO | |
|--|---|
| Site | LAKE CITY HARDWARE |
| Street | 222 S. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | RNE REALTY LLC |
| Parcel ID | 018D E 023.00 and 018D E 024.00 |
| Owner Street | 222 MAIN ST |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map | Figure 2 |
| Figure | Figure 2 |
| Acreage | 0.15 |
| Description | Property lies directly off S. Main Street. Two buildings structurally connected with block |
| Description Square Footage | construction and brick façade. Parking lot attached to property. |
| Square Footage | 4961 |
| Year Constructed | 1900 |
| Regulatory Status of the Site | No regulatory records found |
| Adjoining/Adjacent Properties | Directly across the street from the Martin Funeral Home |
| | 1940-1976 – Low resolution aerial photos in downtown area, no discernable details. |
| Aerial Photographs | 1982-2016 – Downtown district well developed. All building within the area of interest |
| | constructed and operational. |
| City Directories | 2005 – Lake City Hardware 2010 – Arms of Hope Thrift Store 2014-2017 – Address not |
| | listed |
| | 1940 - A mixed variety of structures on site, with large rectangular Store and several |
| Sanborn Maps | smaller dwellings around the property. It appears as though current site structure may |
| | have integrated many of these smaller historic structures. |
| Current Zoning | C-4 (Central Downtown Business District) |
| Current Site Use | Vacant |
| Former Use | Hardware Store |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues (Challenges | Potential for lead based paint and asbestos hazards due to age of buildings. Potential for |
| Environmental Issues/Challenges | vapor migration from off site sources. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$8,000 - \$15,000 |
| ACM/LBP Survey | \$6,000 - \$8,000 |



| Street 408 N. MAIN STREET City, State, Zip Rocky Top, TN, 37769 County Anderson Demor MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN Parcel ID 08M D 022.00 Demor Street P O BOX 392 Cowner City, State, Zip CLINTON, TN 37717 Area of Interest & Associated Map Figure 5 Careage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage 1996 Vear Constructed 1947 Regulatory Status of the Site No regulatory records found. Bordering directly West across Hwy 25W is a Gas Station with two 12,000-gallon, and two |
|--|
| County Anderson MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN Parcel ID 008M D 022.00 Owner Street P O BOX 392 Owner City, State, Zip Area of Interest & Associated Mapeigure Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage 1996 (Year Constructed 1947 Regulatory Status of the Site NCMILLAN WIFE PATRICIA MCMILLAN Anderson MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN ONE MILLAN CHARLIE F AND |
| County MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN Parcel ID 008M D 022.00 Owner Street P O BOX 392 Owner City, State, Zip CLINTON, TN 37717 Area of Interest & Associated Map Figure 5 Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN Parcel ID 008M D 022.00 Owner Street P O BOX 392 Clinton, TN 37717 Area of Interest & Associated Map Eigure Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage (Fear Constructed) Regulatory Status of the Site MCMILLAN CHARLIE F AND WIFE PATRICIA MCMILLAN 008M D 022.00 P O BOX 392 CLINTON, TN 37717 Figure 5 Figure |
| Parcel ID Owner Street POBOX 392 Cunton, TN 37717 Area of Interest & Associated Map rigure Acreage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Guare Footage Year Constructed Regulatory Status of the Site POBOX 392 CLINTON, TN 37717 Figure 5 Figu |
| Dwner Street Dwner City, State, Zip CLINTON, TN 37717 Area of Interest & Associated Map Figure Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Guare Footage Year Constructed Regulatory Status of the Site P O BOX 392 CLINTON, TN 37717 Figure 5 Figure 5 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Figure 5 No regulatory Status of the Site |
| Acrea of Interest & Associated Map Figure 5 Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Gequare Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| Area of Interest & Associated Map Figure 5 Acreage 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Gequare Footage 7 ear Constructed Regulatory Status of the Site Figure 5 1.03 Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. No regulatory Status of the Site |
| Acreage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. |
| Acreage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Gquare Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Gquare Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Foquare Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Foquare Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Foquare Footage Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. |
| Property lies at the intersection between N. Main Street and Mason Avenue. Additional driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| driveway/parking lot provides access from Mason Avenue. Block construction, shingled roof. Stucco siding. Square Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| roof. Stucco siding. Square Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| Square Footage 1996 Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| Year Constructed 1947 Regulatory Status of the Site No regulatory records found. |
| Regulatory Status of the Site No regulatory records found. |
| |
| Rordering directly West across Hwy 25W is a Cas Station with two 12,000 callon and two |
| Adjoining/Adjacent Properties |
| 8,000 gallon gasoline USTs. |
| 1940 – Low resolution aerial photos in downtown area, no discernable details. 1952- 1993 – Residential home on site, very poor photo quality. 1997-2016 – Possible parking lot built, giving the property a hybrid appearance business/residential. |
| Tity Directories 1992 – Address not listed 1995 – R&R Screen Printing 2000-2017 – Address not listed |
| Sanborn Maps 1940 - Private Residence |
| Current Zoning C-1 (General Commercial District) |
| Current Site Use Unknown, believed vacant |
| Former Use Residential |
| FEMA/Flood Zone B |
| National Wetland Inventory Maps No mapped wetlands on the site. |
| Jtilities Available water, sewer, electric, gas |
| Possible residual petroleum contamination related to former USTs on adjoining property. Potential for lead based paint and asbestos hazards due to age of buildings. Potential for |
| vapor migration from on site and off site sources. |
| vapor migration from on site and off site sources. Phase I ESA Fee \$4,000 |
| |



| Site | 506 N Main |
|---|--|
| Street | 506 N. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | NELSON RONALD BARRY NELSON |
| Parcel ID | 008L B 007.00 |
| Owner Street | PO BOX 1215 |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map Figure | Figure 5 |
| Acreage | 0.18 |
| Description | Property lies directly off N. Main Street. Former Residential building. Block construction, shingled roof. |
| Square Footage | 2002 |
| Year Constructed | 1956 |
| Regulatory Status of the Site | No regulatory records found. |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1940 – Low resolution aerial photos in downtown area, no discernable details. 1952-1993 – Residential home on site, very poor photo quality. 1997-2016 – Clear residential site with several outbuildings added to site. |
| City Directories | 1992-1995 – Lake City Reading Center, Third National Bank Lake City Branch 2000-2017 – Address not listed |
| Sanborn Maps | Unmapped Property |
| Current Zoning | C-1 (General Commercial District) |
| Current Site Use | Vacant |
| Former Use | Residential |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric, gas |
| Environmental Issues/Challenges | Possible residual petroleum contamination related to former USTs from sites within a 1/4 radius of site. None directly adjacent. Potential for lead based paint and asbestos hazards due to age of buildings. Potential for vapor migration from on site and off site sources. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$5,000 - \$10,000 |
| ACM/LBP Survey | \$3,000 - \$6,000 |

| | | 1 |
|-------------------|---|----------|
| | | |
| i de | | |
| | A CONTRACT OF THE PARTY OF THE | Ş |
| The second second | | 4 |
| 4.22 | | |
| | | |
| 40 | | Mary Co. |

| Site | 1008 N Main |
|-----------------------------------|---|
| Street | 1008 N. MAIN STREET |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | HOSKINS OIL CO LLC |
| Parcel ID | 008 036.00 |
| Owner Street | 1008 MAIN STREET |
| Owner City, State, Zip | ROCKY TOP, TN 37769 |
| Area of Interest & Associated Map | Figure 7 |
| Figure | riguic / |
| Acreage | 1.31 |
| Description | Property lies directly off N. Main Street. Large, industrial-use property. Multiple tanks, loading sites. |
| Square Footage | Unknown |
| Year Constructed | Unknown |
| Regulatory Status of the Site | One 17,000-gallon and one 11,000-gallon gasoline UST, one 17,000-gallon and one 11,000-gallon ULS Diesel UST, and one 11,000-gallon kerosene UST identified on the site. All of which with a regulatory status of "Currently in Use". An additional 2,000-gallon gasoline UST with a status of "Temporarily Out of Use" is also listed in the UST Databases. A number of LUST and spills have been reported on the site, however all incidents are closed at this time. |
| Adjoining/Adjacent Properties | None identified of environmental concern. |
| Aerial Photographs | 1952-1956 – Site undeveloped. 1973-2016 – Site developed for use, with several building, fueling station, Oil tanks. |
| City Directories | 1992-1995 – Address not listed 2000-2017 – Exxon Company USA Bulk Plant, Purnell Distributors Inc., Hoskins Oil |
| Sanborn Maps | Unmapped Property |
| Current Zoning | C-1 (General Commercial District) |
| Current Site Use | Vacant |
| Former Use | Petroleum Distributor |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric |
| Environmental Issues/Challenges | Residual petroleum contamination related to current USTs on site, and former petroleum-product spills on/near site. Potential for lead based paint and asbestos hazards due to age of buildings. Potential for vapor migration from on site and off site sources. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$25,000 - \$45,000 |
| ACM/LBP Survey | \$5,000 - \$8,000 |



| Site | 502 Norris Freeway |
|-----------------------------------|---|
| Street | 502 NORRIS FREEWAY |
| City, State, Zip | Rocky Top, TN, 37769 |
| County | Anderson |
| Owner | LEE OIL COMPANY INC |
| Parcel ID | 008 099.00 |
| Owner Street | PO BOX 2580 |
| Owner City, State, Zip | MIDDLESBORO, KY 40965 |
| Area of Interest & Associated Map | Firmura C |
| Figure | Figure 6 |
| Acreage | 0.92 |
| Description | Property lies at the intersection between Norris Freeway and Cobb Hollow Road. Gas |
| | station that appears to have been built soon after I-75. No change in use through history |
| | of site. |
| Square Footage | 1396 |
| Year Constructed | 1974 |
| Regulatory Status of the Site | Three 10,000-gallon steel gasoline USTs still on site. Current status labelled as |
| | "Temporarily Out of Use". One historic 3,000-gallon UST/LUST identified on (possibly |
| | adjacent to) site. Regulatory status listed as "Permanently Out of Use" with the LUST |
| | TRUST case status "Closed" |
| Adjoining/Adjacent Properties | Adjacent parcel is a former gas station |
| Aerial Photographs | 1940-1956 – Site undeveloped. 1976 – Construction of interstate system, and |
| | development of site appears to be relatively new. 1982-2016 – Building clearly exists on |
| | site and appears to be in-use/maintained. |
| City Directories | 1999-2009 – Norris Dam BP. |
| Sanborn Maps | Unmapped Property |
| Current Zoning | C-1 (General Commercial District) |
| Current Site Use | Vacant |
| Former Use | Gas Station/Truck Stop |
| FEMA/Flood | Zone B |
| National Wetland Inventory Maps | No mapped wetlands on the site. |
| Utilities Available | water, sewer, electric |
| Environmental Issues/Challenges | Residual petroleum contamination related to current and former USTs on site. Potential |
| | for lead based paint and asbestos hazards due to age of buildings. Potential for vapor |
| | migration from on site and off site sources. |
| Phase I ESA Fee | \$4,000 |
| Phase II ESA Fee | \$15,00-\$25,000 |
| ACM/LBP Survey | \$3,000 - \$6,000 |